NTSB ID: NYC06RA003 Aircraft Registration Number: C-FEXS

Occurrence Date: 10/06/2005 Most Critical Injury: Fatal

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Nearest City/Place Winnipeg	State	Zip Code	Local Time 0540	Time Zone CDT	
Airport Proximity:	Distance Fron	n Landing Facility:		Direction Fro	m Airport:

Aircraft Information Summary

7 in ordine in its initiation. Gainmany		
Aircraft Manufacturer	Model/Series	Type of Aircraft
Cessna	208B	Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On October 6, 2005, about 0540 central daylight time, a Cessna 208B, Canadian registration C-FEXS, operated by Morning Star Air Express as flight 8060, was destroyed when it impacted the ground, after takeoff from Winnipeg International Airport (CYWG), Winnipeg, Manitoba, Canada. The certificated airline transport pilot was fatally injured. Instrument meteorological conditions prevailed and an instrument rules flight plan had been filed for the flight destined for Thunder Bay, Ontario. The cargo flight was conducted under CAR Part 703.

According to a Transportation Safety Board representative, the airplane departed runway 36, and was instructed to perform a right turn on course. Shortly thereafter, the pilot informed air traffic control that she needed to return to the airport due to icing conditions. The airplane impacted on railroad tracks about 4 miles southeast of the airport.

This investigation is under the jurisdiction of the Government of Canada. Further information may be obtained from:

Transportation Safety Board of Canada 335-550 Century Street Winnipeg, Manitoba, Canada R3H 0Y1

This report is for informational purposes only.

NTSB ID: NYC06RA003

Occurrence Date: 10/06/2005

AVIATION		Occurrence Type: Accident											
Landing Facility/Approach In	formation	•											
Airport Name Airp				A	irport Elevati Ft. I	on MSL	Runway Used Runw			way Length		Runv	vay Width
Runway Surface Type:		•											
Runway Surface Condition:													
Type Instrument Approach:													
VFR Approach/Landing:													
Aircraft Information										1			
Aircraft Manufacturer Cessna			Mode 208		ries					Serial	Numbe	er	
Airworthiness Certificate(s):			•										
Landing Gear Type:													
Homebuilt Aircraft? No	Number of Seats:		Certifi	Certified Max Gross Wt.					LBS Numbe			er of Engines:	
Engine Type: En				Engine Manufacturer: Model/Series:								Rate	d Power:
- Aircraft Inspection Information													
Type of Last Inspection			Date of La	Date of Last Inspection Time Since Last Inspection Hou					ours	Airframe Total Time urs Hours			
- Emergency Locator Transmitter (ELT) Information	'											
ELT Installed?	ELT Operat	ted?				ELT .	Aided ii	n Locating Ac	cident S	ite?			
Owner/Operator Information													
Registered Aircraft Owner				Street Address									
	City	City State								Zip Code			
Operator of Aircraft Street Address													
Morningstar Air Express				City State Zi								Zip Code	
Operator Does Business As: Operator Designator Code:													
- Type of U.S. Certificate(s) Held: I	None												
Air Carrier Operating Certificate(s)	:												
Operating Certificate: Operator Certificate:													
Regulation Flight Conducted Under: Non-U.S., Commercial													
Type of Flight Operation Conducted	d: Non-scheduled	l; Dome	stic; Carg	jo									
		FACTU	JAL REP	ORT	- AVIATIO	ON							Page 2

NTSB ID: NYC06RA003

Occurrence Date: 10/06/2005

AVIATION Occurrence Type: Accident													
First Pilot Information													
Name	City				;	State	Da	te of Birth	Age				
On File													
Sex: Seat Occupied	d:	Prir	icipal Profes	sion:					Certifi	cate Nu	mber:	On File	
Certificate(s):													
Airplane Rating(s):													
Rotorcraft/Glider/LTA:	Rotorcraft/Glider/LTA:												
Instrument Rating(s):													
Instructor Rating(s):													
Type Rating/Endorsement f	or Accident/Ir	ncident Aircra	ít?			С	urrent Bi	ennial Flig	ht Rev	view?			
Medical Cert.:	Medica	al Cert. Status	s:					Date o	of Last	Medica	l Exar	m:	
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night In: Actual			Instrument Simulated		Rotorcraft		Glider	Lighter Than Air
Total Time													
Pilot In Command(PIC)													
Instructor													
Last 90 Days													
Last 30 Days													
Last 24 Hours	1						D				0		
Seatbelt Used?	Shou	ılder Harness	Used?			OXICO	ology Peri	ormed?			Seco	nd Pilot?	
Flight Plan/Itinerary						—							
Type of Flight Plan Filed: IF													
Departure Point						State Airport Id		irport Ider	ort Identifier Departu		nartur	rture Time Time Zone	
Same as Accident/Incide	ent Location							CYWG			0540		CDT
Destination State Airport Identifier													
Thunder Bay								CYQT					
Type of Clearance:													
Type of Airspace:													
Weather Information													
Source of Briefing:													
Method of Briefing:													
FACTUAL REPORT - AVIATION Page 3													

NTSB ID: NYC06RA003

Occurrence Date: 10/06/2005

Occurrence Type: A				Accider	nt								
Weather Information													
WOF ID	Observation Time	Time Zone	,	WOF Elevat	WOF Elevation WOF Distance From Acc			n Accid	lent Site		Direction From Ad	cident Site	
CYWG	0531		\perp	Ft.	. MSL				NM	NM De			
Sky/Lowes	st Cloud Condition:						Ft. AG	L	Condition of Light:				
Lowest Ce	eiling: Broken			1000 Ft.	AGL	Visib	oility:	4	SM	"Hg			
Temperatu	ure: -1 °C	Dew Point:		-1 °C	Wind	Direction	: 360			Dei	nsity Altitude:	Ft.	
Wind Spee	ed: 15	Gusts: ;	20		Weather Condtions at Accident Site: Instrument Conditions								
Visibility (R	RVR): Ft.	Visibility	y (RV	V)	SM	Intensi	ty of Precipita	ation:					
Restriction	ns to Visibility:												
Type of Pre	Type of Precipitation:												
Accident	Information												
Aircraft Dar	mage: Destroyed			Aircraft Fire	e:	Aircraft Explo				plosion			
Classificati	ion:												
- Injury Su	mmary Matrix	Fatal	Serio	ous Mino	or	None	TOTAL						
First Pi	ilot	1					1						
Second	d Pilot												
Studen	nt Pilot												
Flight In	nstructor												
Check	Pilot												
Flight E	Engineer												
Cabin /	Attendants												
Other C	Crew												
Passen	ngers												
- TOTAL /	ABOARD -	1					1						
Other G													
- GRANE	D TOTAL -	1					1						
				·									

AVIATION

NTSB ID: NYC06RA003

Occurrence Date: 10/06/2005

Occurrence Type: Accident

Admin	istrative	Information

Investigator-In-Charge (IIC)

Luke Schiada

Additional Persons Participating in This Accident/Incident Investigation:

TR Proven Washington